

Sanitary Sewer Overflow Annual Report

Division of Surface Water

Date:

February 18, 2020

Facility name:

Opalocka WWTP

Ohio NPDES permit no.:

3PH00000*HD

Period covered by report:

January 1, - December 31, 2019

Contact person

Name:

David Osborn II

Title:

Operations Manager

Mailing address:

470 Center Street, Building #3, Chardon OH, 44024

Telephone:

(440)346 - 5953

Email:

daveo@gcdwr.org

Certification:

I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.

Name (typed): David Osborn II

Title:

Operations Manager

Signature:

Date:

EPA 4238 (Rev. 6/14)

SSO Annual Report Table 1: SSO Identification		Barrie Market B	
dentification No. ^A	Location Description	Receiving Water ^B	Eliminated ^c
301	Opalocka WWTP Grounds	SS Unamed Creek	11/18/2019
=			

A. Assign each SSO location a unique identification by numbering them consecutively, beginning with 301.

B. Enter name of receiving water. If an SSO enters a storm sewer, enter "SS to (name of receiving water)." If an SSO does not reach a receiving water, enter (None".

C. If an SSO has been eliminated, enter the date of elimination (MM/DD/YY).

SSO Annual Report Table 2: SSO Event Information Ohio NPDES Permit No.: 3PH00000*HD				
Date ^A	Date ^A Identification No. ^B		Receiving Water ^C	
11/17/2019	301	SS- Unamed Tributary of the Chagrin River		.00050025 MGE
	,			
		-		

- A. Enter date as "MM/DD/YY". Enter "Various" to summarize overflows of less than 1000 gallons from an SSO location
- B. Enter the unique identification assigned in Table 1.
- C. Enter name of receiving water. If an SSO enters a storm sewer, enter "SS to (name of receiving water)." If an SSO does not reach a receiving water, enter "None".
- D. Enter estimate of volume in MG (million gallons). Enter estimate of total volume if summarizing data.

Use additional pages as needed.

O Annual Report Table 3: Water in Basement Occurrences		Ohio NPDES Permit No.: 3PH00000*HD	
wershed ^A	WIB Occurrences	s ^B Causes ^c	
otal Occurrences			

A. A sewershed is a specific geographic area, such as a city block or a subdivision, that drains to a common outlet.

Use additional pages as needed.

B. Enter the total number of water in basement occurrences report for the sewershed.

C. Enter all causes that apply: W = extreme weather; E = equipment failure; P = power failure; D = debris in line; R = roots; G = grease; B = other blockages; L = Line deterioration; V = vandalism; O = other, prove details.

SSO Annual Report: Water in Basement Narratives	Ohio NPDES Permit No.: 3PH00000*HD				
narrative analysis of WIB patterns by location, frequency and cause.					

EPA 4238 (Rev. 6/14)